



MISSOURI-KANSAS CITY BASIN



LAKE CHATEAU DAM

BOONE COUNTY, MISSOURI

MO. 10015

MA105329

PHASE 1 INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM



St. Louis District

PREPARED BY: U.S. ARMY ENGINEER DISTRICT, ST. LOUIS

FOR: STATE OF MISSOUR

This document has been approved for poblic release and sale; its distribution is unlimited.

DTIC ELECTE 0CT 1 3 1981

MAY, 1979

81 10 9 027

E8

UNCLASSIFIED
SECURITY CLASSIFICATION OF THIS PAGE (When Date Britered)

REPORT DOCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM	
1. REPORT NUMBER 2. GOVT ACCESSION	ON NO. 3. RECIPIENT'S CATALOG NUMBER	
AD AJOS	329	
4. TITLE (and Subsitio) Phase I Dam Inspection Report	5. TYPE OF REPORT & PERIOD COVERED	
	7	
National Dam Safety Program	Final Reperce	
Lake Chateau Dam (MO 10015) Boone County, Missouri	6. PERFORMING ORG REPORT NUMBER	
C. AUTHOR(e)	8. CONTRACT OR GRANT NUMBER(*)	
Hoskins-Western-Sonderegger, Inc.		
	-,	
	DACW43-79-C-6646 V	
9. PERFORMING ORGANIZATION NAME AND ADDRESS	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS	
U.S. Army Engineer District, St. Louis		
Dam Inventory and Inspection Section, LMSED-PD		
210 Tucker Blvd., North, St. Louis, Mo. 63101		
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis	May 1979	
Dam Inventory and Inspection Section, LMSED-PD	13. NUMBER OF PAGES	
210 Tucker Blvd., North, St. Louis, Mo. 63101	Approximately 65	
14. MONITORING AGENCY NAME & ADDRESS(If different from Controlling O		
	,	
Rey S. /Decker Gordon /Jamison	UNCLASSIFIED	
Rey S. /Decker Gordon /Jamison Michael /McMeekin Harold P. /Hoskins	154. DECLASSIFICATION/DOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report)		
16. DISTRIBUTION STATEMENT (of this report)	(121)	
Annuaved for polonger distribution unlimited		
Approved for release; distribution unlimited.		
	and the second of the second o	
National Dam Safety Program.	Lake ·	
17. DISTRIBUTION ST Chateau Dam (MO 10015), Missour		
City Basin, Boone County, Misso	ouri.	
Phase I Inspection Report.	- was a subject of the subject of th	
18. SUPPLEMENTARY NOTES		
]		
j		
1		
19. KEY WORDS (Continue on reverse side if necessary and identify by block	number)	
Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side N necessary and identify by block r	nahar)	
This report was prepared under the National Pro		
	eral condition of the dam with	
respect to safety, based on available data and on visual inspection, to		
determine if the dam poses hazards to human lif	e or property.	
	ł	
1		

DD 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOLETE UNCLASSIFIED

394131 SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

R

CI ba

Cŧ

B4

INSTRUCTIONS FOR PREPARATION OF REPORT DOCUMENTATION PAGE

RESPONSIBILITY. The controlling DoD office will be responsible for completion of the Report Documentation Page, DD Form 1473, in all technical reports prepared by or for DoD organizations.

CLASSIFICATION. Since this Report Documentation Page, DD Form 1473, is used in preparing announcements, bibliographies, and data banks, it should be unclassified if possible. If a classification is required, identify the classified items on the page by the appropriate symbol.

COMPLETION GUIDE

- General. Make Blocks 1, 4, 5, 6, 7, 11, 13, 15, and 16 agree with the corresponding information on the report cover. Leave Blocks 2 and 3 blank.
 - Block 1. Report Number. Enter the unique alphanumeric report number shown on the cover.
 - Block 2. Government Accession No. Leave Blank. This space is for use by the Defense Documentation Center.
- Block 3. Recipient's Catalog Number. Leave blank. This space is for the use of the report recipient to assist in future retrieval of the document.
- Block 4. Title and Subtitle. Enter the title in all capital letters exactly as it appears on the publication. Titles should be unclassified whenever possible. Write out the English equivalent for Greek letters and mathematical symbols in the title (see "Abstracting Scientific and Technical Reports of Defense-sponsored RDT/E,"AD-667 000). If the report has a subtitle, this subtitle should follow the main title, be separated by a comma or semicolon if appropriate, and be initially capitalized. If a publication has a title in a foreign language, translate the title into English and follow the English translation with the title in the original language. Make every effort to simplify the title before publication.
- Block 5. Type of Report and Period Covered. Indicate here whether report is interim, final, etc., and, if applicable, inclusive dates of period covered, such as the life of a contract covered in a final contractor report.
- Block 6. Performing Organization Report Number. Only numbers other than the official report number shown in Block 1, such as series numbers for in-house reports or a contractor/grantee number assigned by him, will be placed in this space. If no such numbers are used, leave this space blank.
- Block 7. Author(s). Include corresponding information from the report cover. Give the name(s) of the author(s) in conventional order (for example, John R. Doe or, if author prefers, J. Robert Doe). In addition, list the affiliation of an author if it differs from that of the performing organization.
- Block 8. Contract or Grant Number(s). For a contractor or grantee report, enter the complete contract or grant number(s) under which the work reported was accomplished. Leave blank in in-house reports.
- Block 9. Performing Organization Name and Address. For in-house reports enter the name and address, including office symbol, of the report and identify the appropriate corporate division, school, laboratory, etc., of the author. List city, state, and ZIP Code.
- Block 10. Program Element, Project, Task Area, and Work Unit Numbers. Enter here the number code from the applicable Department of Defense form, such as the DD Form 1498, "Research and Technology Work Unit Summary" or the DD Form 1634. "Research and Development Planning Summary," which identifies the program element, project, task area, and work unit or equivalent under which the work was authorized.
- Block 11. Controlling Office Name and Address. Enter the full, official name and address, including office symbol, of the controlling office. (Equates to funding/sponsoring agency. For definition see DoD Directive 5200.20, "Distribution Statements on Technical Documents.")
 - Block 12. Report Date. Enter here the day, month, and year or month and year as shown on the cover.
 - Block 13. Number of Pages. Enter the total number of pages.
- Block 14. Monitoring Agency Name and Address (if different from Controlling Office). For use when the controlling or funding office does not directly administer a project, contract, or grant, but delegates the administrative responsibility to another organization.
- Blocks 15 & 15s. Security Classification of the Report: Declassification/Downgrading Schedule of the Report. Enter in 15 the highest classification of the report. If appropriate, enter in 15a the declassification/downgrading schedule of the report, using the abbreviations for declassification/downgrading schedules listed in paragraph 4-207 of DoD 5200.1-R.
- Block 16. Distribution Statement of the Report. Insert here the applicable distribution statement of the report from DoD Directive 5200.20, "Distribution Statements on Technical Documents."
- <u>Block 17.</u> Distribution Statement (of the abstract entered in Block 20, if different from the distribution statement of the report). Insert here the applicable distribution statement of the abstract from DoD Directive 5200.20, "Distribution Statements on Technical Documents."
- Block 18. Supplementary Notes. Enter information not included elsewhere but useful, such as: Prepared in cooperation with . . . Translation of (or by) . . . Presented at conference of . . . To be published in . . .
- Block 19. Key Words. Select terms or short phrases that identify the principal subjects covered in the report, and are sufficiently specific and precise to be used as index entries for cataloging, conforming to standard terminology. The DoD "Thesaurus of Engineering and Scientific Terms" (TEST), AD-672 000, can be helpful.
- Block 20: Abstract. The abstract should be a brief (not to exceed 200 words) factual summary of the most significant information contained in the report. If possible, the abstract of a classified report should be unclassified and the abstract to an unclassified report should consist of publicly- releasable information. If the report contains a significant bibliography or literature survey, mention it here. For information on preparing abstracts see "Abstracting Scientific and Technical Reports of Defense-Sponsored RDT&E," AD-667 000.

LAKE CHATEAU DAM BOONE COUNTY, MISSOURI MISSOURI IDENTIFICATION NO. 10015

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM

PREPARED BY HOSKINS-WESTERN-SONDEREGGER, INC. CONSULTING ENGINEERS LINCOLN, NEBRASKA

UNDER DIRECTION OF

ST. LOUIS DISTRICT, CORPS OF ENGINEERS

FOR

GOVERNOR OF MISSOURI

MAY, 1979

TIS GRA&I ITIC TAB Becamounced Justification Distribution/

Ivailability Codes

Andil anl/or I phoid!



DEPARTMENT OF THE ARMY

ST. LOUIS DISTRICT, CORPS OF ENGINEERS
210 TUCKER BOULEVARD, NORTH
ST. LOUIS, MISSOURI 63101

LMSED-FI

SUBJECT: Lake Chateau Dam Phase I Inspection Report

This report presents the results of field inspection and evaluation of the Lake Chateau Dam (Mo. 10015).


It was prepared under the National Program of Inspection of Non-Federal Dams.

This dam has been classified as unsafe, emergency by the St. Louis District as a result of the application of the following criteria:

- a. Spillway will not pass a 10-year frequency flood without overtopping of the dam. The spillway is, therefore, considered to be unusually small and seriously inadequate.
 - b. Overtopping could result in dam failure.
- c. Dam failure significantly increases the hazard to life and property downstream.

SIGNED

Submitted By:	1 2 MAY 1980
Chief, Engineering Division	Date
SIGNED	
Approved By:	1 3 MAY 1980 _
Colonel, CE, District Engineer	Date



PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM

TABLE OF CONTENTS

PARAGRAPH	NO. TITLE	PAGE NO.
	Assessment Summary	
	Overview Photograph	
	SECTION 1 - PROJECT INFORMATION	
1.1 1.2 1.3	General Description of Project Pertinent Data	1 1 3
	SECTION 2 - ENGINEERING DATA	
2.1 2.2 2.3 2.4	Design Construction Operation Evaluation	6 6 6
	SECTION 3 - VISUAL INSPECTION	
3.1 3.2	Findings Evaluation	7 9
	SECTION 4 - OPERATIONAL PROCEDURES	
4.1 4.2 4.3 4.4 4.5	Procedures Maintenance of Dam Maintenance of Operating Facilities Description of Any Warning System in Effect Evaluation	10 10 10 10 10
	SECTION 5 - HYDRAULIC/HYDROLOGIC	
5.1	Evaluation of Features	11
	SECTION 6 - STRUCTURAL STABILITY	
6.1	Evaluation of Structural Stability	13
	SECTION 7 - ASSESSMENT/REMEDIAL MEASURES	
7.1 7.2	Dam Assessment Remedial Measures	14 14

APPENDIX A - MAPS

Plate A-1	Vicinity Photography		
Plate A-2	Location Map		
	APPENDIX B - PHOTOGRAPHS		
Plate B-1	Photo Index		
Plate B-2	Photo No. 2 - Overview Taken from Upstream on Left Side		
	Photo No. 3 - Looking Downstream in Gully Located at Left End of Dam		
Plate B-3	Photo No. 4 - Upstream Slope from Left End.		
Plate B-4	Photo No. 5 - Upstream from Left End Photo No. 6 - Crest Taken from Left End		
riace D-4	Photo No. 7 - Downstream Slope from Left End.		
Plate B-5	Photo No. 8 - Sewage Lagoons Downstream on Left		
	Photo No. 9 - Principal Spillway Outlet and		
	Stilling Basin		
Plate B-6	Photo No.10 - Looking Downstream into Stilling		
	Basin and Outlet Channel		
Plate B-7	Photo No.11 - Downstream Slope Taken from Right Photo No.12 - Looking Upstream in Emergency Spillway		
Plate b-/	Photo No.12 - Looking Opstream in Emergency Spillway		
Plate B-8	Photo No.14 - Gully in Spillway Exit Channel		
i idice bio	Photo No.15 - Inlet of Principal Spillway		
	APPENDIX C - PROJECT PLATES		
Plate C-1	Phase 1 - Plan of Dam		
Plate C-2	Phase 2 - Centerline Profile of Main Dam & Centerline		
	Profile of Levee Extension		
Plate C-3	Phase 3 - Cross Section of Dam at Sta. 3+50		
	APPENDIX D		
	HYDRAULIC AND HYDROLOGIC DATA		
Plates D-1 & D-2 Hydrologic Computations			
Plate D-3	Principal Spillway Rating Curve		
Plate D-4	Emergency Spillway Rating Curve		
Plate D-5	PMF Routing Curve		
Plates D-6 to 1 Plates D-23 to			
riates U-23 to	0-40 compared tubur and outhor for to-year clood		

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM ASSESSMENT SUMMARY

Name of Dam State Located County Located Stream

Lake Chateau Dam Missouri Boone County

Date of Inspection

Tributary Little Cedar Creek

May 31, 1979

Lake Chateau Dam was inspected by an interdisciplinary team of engineers from Hoskins-Western-Sonderegger, Inc. The purpose of the inspection was to make an assessment of the general conditions of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

The guidelines used in the assessment were furnished by the Department of the Army, Office of the Chief of Engineers and developed with the Kelp of several Federal and State agencies, professional engineering organizations, and private engineers. Based on these guidelines, this dam is classified as a small size dam with a high downstream hazard potential. Failure would threaten life and property. The estimated damage zone extends approximately 1/2 mile downstream of the dam. Within the damage zone are two dwellings and Highway WW.

Our inspection and evaluation indicates that the spillways do not meet the criteria set forth in the recommended guidelines for a small dam having a high hazard potential. Considering the volume of water impounded and the large downstream floodplain, one-half of the Probable Maximum Flood is the appropriate spillway design flood. The spillways for this dam will not pass the 100-year flood (flood having a one percent chance of being exceeded in any year) nor will it pass the 10-year flood without overtopping the levee extension of the dam. The spillways have the capacity to pass five percent of the Probable Maximum Flood without overtopping the levee extension. The Probable Maximum Flood (PMF) is defined as the flood that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region.

This dam is severely deficient in spillway capacity. Recommendations presented in Paragraph 7.2a of this report are as follows:

1) The height of the levee extension should be increased to equal the height of the main dam. The size of the emergency spillway should be increased and/or the emergency spillway should be lowered in order to pass one-half of the Probable Maximum Flood.

- 2) Measures should be taken to control the erosion of the existing channel that is cut through the left abutment of the main dam.
- 3) Seepage and stability analyses comparable to the "Recommended Guidelines for Safety Inspection of Dams" should be obtained.

These recommendations should be pursued immediately.

Other deficiencies observed during the inspection are trees and shrubs growing on both slopes, seepage along the toe and erosion of the upstream slope. Recommendations covering these items are presented in Paragraph 7.2b.

Michael McMeekin

E-4776

Chairman of Board

Hoskins-Western-Sonderegger, Inc.

E-8696



PHOTO NO. 1 - OVERVIEW

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM LAKE CHATEAU DAM - MO 10015 BOONE COUNTY, MISSOURI

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

- a. Authority. The National Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army through the Corps of Engineers, to initiate a program of safety inspection of dams throughout the United States. Pursuant to the above, the St. Louis District, Corps of Engineers, District Engineer directed that a safety inspection of Lake Chateau Dam be made.
- b. <u>Purpose of Inspection</u>. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.
- c. Evaluation Criteria. Criteria used to evaluate the dam were furnished by the Department of the Army, Office of the Chief of Engineers, in "Recommended Guidelines for Safety Inspection of Dams," Appendix D to "Report of the Chief of Engineers on the National Program of Inspection of Dams," dated May, 1975, and published by the Department of the Army, Office of the Chief of Engineers.

1.2 DESCRIPTION OF PROJECT

- a. Description of Dam and Appurtenances.
 - (1) The main dam is an earth fill about 30.5 feet in height and 800 feet long. A levee about 3 to 4 feet in height and approximately 250 feet in length extends westward from the north (left) end of the dam. The levee diverts drainage from approximately 27 acres to the north of the dam (see plate A-1) through an eroded channel cut through the left abutment of the main dam. A very small pond is located on the north side of the levee. Overflow from this pond flows along the north side of the levee through the eroded channel in the left abutment of the main dam. Three sewage lagoons are located downstream from the dam. Two of the lagoons are immediately downstream of the toe of the dam on the

left end. The third lies to the north and is located high on the left abutment. The continuation of the channel referred to above is located between the higher lagoon and the northernmost lagoon at the toe of the

The dam and levee extension are constructed in gently rolling topography. Soils in the area are probably Keswick and Findley developed on thin loess and fine grained glacial till overlying limestone.

- (2) The principal spillway consists of a 6 foot diameter steel pipe riser with a 30 inch diameter welded steel pipe conduit passing through the embankment.
- (3) A vegetated earth emergency spillway is cut through the right abutment.
- (4) Pertinent physical data are given in paragraph 1.3 below.
- b. Location. The dam is located in the east central portion of Boone County, Missouri, as shown on Plate A-2. The dam is shown on Plate A-1 in the NE¼ of Section 29, T48N, R11W. The lake formed behind the dam is shown in the NE¾ of Section 29, T48N, R11W.
- c. <u>Size Classification</u>. Criteria for determining the size classification of dams and impoundments are presented in the guidelines referenced in paragraph 1.1c above. Based on these criteria, this dam and impoundment is in the small size category.
- d. Hazard Classification. Guidelines for determining hazard classification are presented in the same guidelines as referenced in paragraph 1.1c above. Based on referenced guidelines, this dam is in the high hazard classification. The estimated damage zone extends for about one-half mile downstream. The channel from the dam enters the larger Little Cedar Creek about one-fourth mile downstream from the dam. Improved Highway WW crosses Little Cedar Creek about 600 feet upstream from the subject confluence. Two dwellings occupy the high flood plain of Little Cedar Creek about 0.5 miles downstream from the dam.
- e. Ownership. The dam is owned by Lake Chateau, Inc., c/o William Castle, Route 2, Columbia, Missouri 65201.

- f. <u>Purpose of Dam</u>. The dam impounds a recreational lake covering about 25 acres with normal storage of 183+ acre feet.
- g. Design and Construction History. Some very preliminary design assistance was provided by the Soil Conservation Service (SCS) for this dam. The dam was constructed in 1964. It was reported by the SCS that about 1966 some of the welds failed on the pipe spillway, and a portion of the downstream slope was eroded out. The pipe was uncovered and repaired and the damaged downstream slope was rebuilt.
- h. <u>Normal Operating Procedure</u>. There are no controlled outlets for this dam. The reservoir level is governed by rainfall, infiltration, evaporation and the capacity of the uncontrolled spillways.

1.3 PERTINENT DATA

- a. Drainage Area. 1.26 sq. mi. (808 acres).
- b. Discharge At Damsite.
 - (1) All discharges at the damsite are through the principal spillway pipe or the vegetated earth emergency spillway or over the levee on the left side of the embankment. Discharge over the levee will exceed the discharge through the emergency spillway.
 - (2) Estimated maximum flood Unknown.
 - (3) The principal spillway capacity varies from 0 c.f.s. at elevation 802.2 (riser crest) to 122 c.f.s. at elevation 804.3 (minimum crest elevation of levee) to 127 c.f.s. at elevation 806.5 (minimum crest elevation of main dam).
 - (4) The emergency spillway capacity varies from 0 c.f.s. at its crest elevation of 805.0 to 320 c.f.s. at elevation 806.5 (minimum crest elevation of dam).
 - (5) Discharge over the levee varies from 0 c.f.s. at the minimum crest elevation of 804.3 to 140 c.f.s. at elevation 805.0 (emergency spillway crest) to 2290 c.f.s. at elevation 806.5 (minimum crest elevation of main dam).

- (6) Total discharge at the minimum crest elevation of the main dam including discharges over the levee at the left end is 2740 c.f.s.
- c. Elevations (Feet above M.S.L.)
 - (1) Top of dam 806.5+ (minimum-main dam) 804.3+ (minimum-levee)
 - (2) Principal spillway crest 802+
 - (3) Emergency spillway crest 805+
 - (4) Streambed at center line 776+
 - (5) Maximum tail water Unknown
- d. Reservoir. Length (feet) of maximum pool 2,400+
- e. Storage (Acre-feet).
 - (1) Top of dam 330+
 - (2) Principal spillway crest 183+
- f. Reservoir Surface (Acres).
 - (1) Top of dam -33+
 - (2) Principal spillway crest 25+
- g. <u>Dam</u>.
 - (1) Type earth fill
 - (2) Length 800 feet+ (main dam) with 250 feet+ levee on left end.
 - (3) Height Minimum = 30.5 feet+, maximum 32 feet+
 - (4) Top width 12 feet +
 - (5) Side slopes.
 - (a) Downstream 2.5H on 1V (measured)
 - (b) Upstream 3.8H on 1V (measured, exposed)
 - (6) Zoning- unknown
 - (7) Impervious core unknown
 - (8) Cutoff unknown
 - (9) Grout curtain unknown
 - (10) Wave protection none
- h. Diversion Channel and Regulating Tunnel. None
- i. Spillway
 - (1) Principal

- (a) Type Uncontrolled drop inlet with 6 foot diameter steel riser and 30 inch diameter steel pipe conduit.
- (b) Crest (invert) elevation 802.2 feet+ Outlet - (invert) elevation - 777.5 feet+
- (c) Length 90 feet+

(2) Emergency

- (a) Type well vegetated earth, uncontrolled spillway located on right end of dam, 80 footbottom width.
- (b) Control section 80 feet+ wide, 50 feet+ long.
- (c) Crest elevation 805 feet+
- (d) Upstream Channel vegetated, about 50 feet in length on very flat slope.
- (e) Downstream Channel vegetated and open on 3% to 16.5% slope.
- j. Regulating Outlets. None

SECTION 2 - ENGINEERING DATA

2.1 DESIGN

No design data was available for this dam.

2.2 CONSTRUCTION

No construction data were available. It was reported by S.C.S. personnel that the dam was built in 1964.

2.3 OPERATION

No data were available on spillway operation.

2.4 EVALUATION

- a. Availability. No data were available.
- b. Adequacy. The field surveys and visual observation presented herein are considered adequate to support the conclusion of this report. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions (including earthquake loads) and made a matter of record.
- c. <u>Validity</u>. Not applicable.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

a. General. A visual inspection of the Lake Chateau Dam was made on May 31, 1979. Engineers from Hoskins-Western-Sonderegger, Inc., Lincoln, Nebraska, making the inspection were: Rey S. Decker, Geotechnical; Gordon Jamison, Hydrology; and Michael McMeekin, Civil Engineer. The owner was contacted by telephone but was not present during the inspection.

b. Dam.

- (1) Geology and Soils (abutment and embankment). The abutments consist of glacial till over limestone. What appeared to be thick bedded, massive limestone (probably Jefferson City) is exposed in the right abutment spillway cut but was not observed in the left abutment. Valley alluvium consists of CL-ML soils underlain by gravelly materials. Borings on the embankment crest indicate about 2 feet of CL-ML soil high in silt with good CL-CH soils below that depth. Soils on the downstream slope are CL-CH.
- (2) Upstream Slope. The upstream slope is well vegetated from the crest down to about half way to the lake level. At this elevation (804 feet or 805 feet) wave wash has eroded the face to an almost vertical slope. A number of cottonwoods and willows ranging up to 3-inch diameter are growing on the face. No rodent holes or abnormal deformations were noted on the upstream slope.
- (3) Crest. The crest is very well vegetated with adapted grasses. No slides, rodent holes, cracks or abnormal deformations were noted along the crest. The profile of the crest of the main dam is quite uneven, with as much as 1.4 feet variance in elevation between & station 2+00 and 4+50. The crest line of the levee or diversion on the left end of the dam is fairly uniform but is about 2.2 feet lower in elevation than the main dam and about 0.7 feet lower than the crest of the emergency spillway. No evidence of overtopping was noted.
- (4) Downstream Slope. The downstream slope is heavily vegetated with grass and many shrubs and trees ranging up to 6-inches in diameter. Two sewage lagoons are located along the left end of the dam about 20 feet

downstream from the toe of the dam. Seepage outcrops along the toe in the left abutment trough from about station 0+30 to 2+30. Most of the seepy area extends up the downstream slope to an elevation 2 or 3 feet above the toe. The seep area is confined to the area left of the principal spillway outlet between the toe of the dam and the sewage lagoon which undoubtedly influences the subsurface drainage characteristics of this area. Discharge from the seep area was moving so slowly that it was not possible to estimate the quantity of flow. Borings at the toe of the dam to the right of the pipe spillway outlet show groundwater at depths of 2.5 to 3 feet below the surface. No slides or deformation were noted on the downstream slope.

(5) Miscellaneous. The main dam and the levee extension are well vegetated. The levee extension could probably withstand the overtopping to be expected from the ten year flood if it were not for the eroded condition of the channel that carries the water through the left abutment of the main dam. Prolonged flows through this channel could accelerate the headcutting of the channel and could result in breaching of the reservoir prior to overtopping of the main dam.

c. Appurtenant Structures

- (1) Principal Spillway. The principal spillway appears to be in good condition. The lake level was slightly below the crest of the riser when inspected.
- (2) Emergency Spillway. The emergency spillway is well vegetated with grass. A few small trees are growing in the entrance. The upstream face of the entrance has eroded to nearly vertical from normal pool elevation up about 3.5 feet. There was no evidence that the spillway has operated. Limestone is exposed or covered with a few inches of topsoil in the outlet channel and part of the control section of the spillway. The small gulley (1 to 2 feet deep by 1 foot wide) eroded in the left side of the exit channel appears to be the result of abutment runoff. Spillway discharges will probably encroach on the downstream toe of the dam, as discussed in section 5 of this report. The extension of the dam on the left end is approximately the same elevation as the emergency spillway.

- (3) Drawdown facilities. There were no drawdown facilities observed at this dam.
- Reservoir Area. No significant wave wash was observed around the shoreline. No slump or slides were observed.
- e. <u>Downstream Channel</u>. The scour hole for the pipe spillway is well armored with cherty gravel and limestone cobble and appears to be stable. The creek channel below the scour hole is overgrown with trees and brush. The outlet channel for the side drainage around the left end of the dam is quite badly eroded.

3.2 EVALUATION

The dam appears to be in good shape except for lack of maintenance in controlling tree growth. The embankment slopes should provide adequate safety against shear failure for a dam of this height. Seepage along the left end of the downstream slope does not appear to be critical. Overtopping of the main dam should not cause serious damage. However, it would appear that overtopping of the left extension (levee) of the dam would occur before emergency spillway discharge. Such overtopping could accelerate the gully erosion in the left abutment trough and could lead to ultimate breaching of the reservoir.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

There are no controlled outlet works for this dam. The pool level is controlled by rainfall, evaporation and the capacity of the uncontrolled spillways.

4.2 MAINTENANCE OF DAM

Maintenance has been lax in not controlling tree growth on the dam and erosion in the left abutment trough.

4.3 MAINTENANCE OF OPERATING FACILITIES

No operating facilities exist at this dam.

4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

There is no warning system in effect for this dam.

4.5 EVALUATION

There does not appear to be any serious potential of failure of this structure.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

- a. Design Data. No design data were available for Lake Chateau Dam.
- b. Experience. There are no available records of reservoir operation or frequency of emergency spillway operation.
- c. Visual Observations.
 - (1) The principal spillway, consisting of a 30 inch diameter steel pipe with a 6 foot diameter steel pipe riser, is in good condition.
 - (2) The earth emergency spillway on the right abutment of the dam is well-vegetated. The upstream face of the spill-way entrance channel is eroded to a vertical slope for approximately 3.5 feet above the reservoir normal pool. A gully is eroded in the left side of the spillway exit channel. Discharges from the emergency spillway will flow along the downstream toe of the dam.
 - (3) Elevations of the east-west levee at the left end of the dam, which diverts local drainage from the north around the main dam, are approximately 2.2 feet lower than the main dam elevations and approximately 0.7 feet lower than the emergency spillway crest. Flood flows, therefore, will overtop this levee prior to the occurrence of emergency spillway flow and prior to overtopping the main dam. Flows overtopping the levee will discharge into an eroded channel which is cut through the left abutment of the main dam.
- d. Overtopping Potential. According to the guidelines of the Department of the Army, Office of the Chief of Engineers, Lake Chateau Dam is classified as having a high hazard rating and a small size. One half of the Probable Maximum Flood (PMF) to the PMF, therefore, is the recommended design flood for evaluation of the adequacy of the dam and its spillways.

The existing spillways will not pass the 10-year flood, the 100-year flood or one-half of the Probable Maximum Flood without overtopping the levee extension of the dam. Prolonged flows in the channel cut through the left abutment from overtopping of the levee could accelerate the headcutting of the channel and could result in breaching of the reservoir.

<u>Flood</u>	Peak Inflow Discharge c.f.s.	Peak Outflow Discharge c.f.s.	Maximum Pool Elevation	Freeboard * Top of Dam Min. Elev. 804.3	Duration of Dam Overtopping Hrs.
10 yr.	1600	800	805.5	-1.2'	7+
100 yr.	2700	2100	806.2	-1.9'	9+
0.50 PMF	5000	4700	807.1	-2.8'	15+
PMF	9900	9800	808.1	-3.8'	16+
0.05 PMF	500	100	804.3	0.0	0

*Minimum top of dam elevation shown is for the levee extension of the dam. Minimum top of dam elevation for the main dam is 806.5.

The drainage area of the Lake Chateau Dam watershed was determined from the U.S.G.S. Millersburg, Missouri, $7\frac{1}{2}$ -minute topographic quadrangle map. Reservoir surface area and elevation-storage data were also determined from this map. Computations for spillway and dam overtopping discharge ratings were based on surveys made during the field inspection. Hydraulic and hydrologic computations are described in Appendix D.

The estimated downstream damage zone is described in paragraph 1.2d of this report.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

- a. Visual Observation. This dam appears to be structurally stable. The side slopes and apparent materials in the dam would provide adequate safety against shear failures. The effects of seepage forces on stability are not known. The heavy tree growth on the downstream slope could ultimately affect the structural integrity of the dam.
- b. <u>Design and Construction Data</u>. No design or construction data were available. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency.
- c. Operating Records. There are no controlled operating facilities for this dam.
- d. Post Construction Changes. It was reported by S.C.S. personnel that some of the welds in the pipe spillway conduit failed about 2 years after construction and that part of the downstream section was damaged by erosion. The pipe was excavated and repaired and the affected section of the downstream slope was rebuilt.
- e. <u>Seismic Stability</u>. This dam is located in Seismic Zone 1. An earthquake of the magnitude predicted in this area is not expected to cause structural failure of this dam.

SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

7.1 DAM ASSESSMENT

- a. <u>Safety</u>. Overtopping of the levee extension of this dam for prolonged periods could cause breaching of the reservoir. Analyses presented in Section 5 indicate that the levee would be overtopped by 2.8 feet for a period of more than 15 hours by one-half the probable maximum flood. The effects of seepage through the left end of the dam are not known. Additional studies would be required to determine the effects of full load seepage pressures on the structural stability and of overtopping on the structural and erosional stability of the dam. Tree growth on the downstream slope could result in potential of failure of this dam. Seepage and stability analyses comparable to the requirements of the guidelines were not available which is considered a deficiency.
- b. Adequacy of Information. Due to the lack of engineering data, the conclusions in this report are based upon performance history and visual observations. Seepage and stability analyses comparable to the requirements of the guidelines were not available which is considered a deficiency.
- c. <u>Urgency</u>. The items recommended in paragraph 7.2.a should be pursued immediately.
- d. <u>Necessity for Phase II</u>. Phase II investigation is not considered necessary.
- e. <u>Seismic Stability</u>. This dam is located in Seismic Zone 1. An earthquake of this magnitude is not expected to be hazardous to this dam.

7.2 REMEDIAL MEASURES

a. Alternatives.


- (1) The height of the levee extension should be increased to equal the height of the main dam. The size of the emergency spillway should be increased and/or the emergency spillway should be lowered in order to pass 50 percent of the Probable Maximum Flood.
- (2) Measures should be taken to control the erosion of the existing channel that is cut through the left abutment of the main dam.


- (3) Seepage and stability analyses comparable to the "Recommended Guidelines for Safety Inspection of Dams" should be obtained.
- (4) The services of an engineer experienced in the design and construction of dams should be obtained to evaluate the existing dam and spillway, make the necessary analyses and to design the required protective measures.

b. 0 & M Procedures.


- (1) Trees and shrubs growing on both embankment slopes should be removed and measures taken to prevent their recurrence. Removal and after-treatment of trees larger than 3 to 4 inches in diameter should be done under supervision of an engineer experienced in design and construction of earth dams.
- (2) Measures should be taken to repair and control the erosion on the upstream face of the dam.
- (3) A program of regular inspection and maintenance should be initiated to prevent and/or control the deficiencies discussed above. This program should include monitoring the seepage along the downstream toe to determine changes in amount and clarity of the effluent.

APPENDIX A MAPS





APPENDIX B PHOTOGRAPHS






PHOTO NO. 2 - OVERVIEW TAKEN FROM UPSTREAM ON LEFT SIDE




PHOTO NO. 3 - LOOKING DOWNSTREAM IN GULLY LOCATED AT LEFT END OF DAM



PHOTO NO. 4 - UPSTREAM SLOPE FROM LEFT END. NOTE VERTICAL FACE AND TREE GROWTH.




PHOTO NO. 5 - UPSTREAM FROM LEFT END



PHOTO NO. 6 - CREST TAKEN FROM LEFT END



PHOTO NO. 7 - DOWNSTREAM SLOPE FROM LEFT END. AUGER LOCATED NEAR YELLOW BLOOM AT EXTREME RIGHT IS SET IN SEEP OUTCROP. NOTE TREE GROWTH.



PHOTO NO. 8 - SEWAGE LAGOONS DOWNSTREAM ON LEFT.



PHOTO NO. 9 - PRINCIPAL SPILLWAY OUTLET AND STILLING BASIN.



PHOTO NO. 10 - LOOKING DOWNSTREAM INTO STILLING BASIN AND OUTLET CHANNEL.



PHOTO NO. 11 - DOWNSTREAM SLOPE TAKEN FROM RIGHT. NOTE TREE GROWTH.



PHOTO NO. 12 - LOOKING UPSTREAM IN EMERGENCY SPILLWAY. TREES GROWING IN ENTRANCE.



PHOTO NO. 13 - LOOKING DOWNSTREAM IN EMERGENCY SPILLWAY.



PHOTO NO. 14 - GULLY IN SPILLWAY EXIT CHANNEL







PHOTO NO. 15 - INLET OF PRINCIPAL SPILLWAY

APPENDIX C PROJECT PLATES








MAIN DAM SECTION

@ STA. 3+50

Scale: 1"-70"H

1"=10"V.



SPILLWAY CENTERLINE PROFILE
Scale: 1" 50" H
1" 10" V.

APPENDIX D HYDRAULIC AND HYDROLOGIC DATA

HYDROLOGIC COMPUTATIONS

- 1. The SCS dimensionless unit hydrograph and the systemized computer program HEC-1 (Dam Safety Version), July, 1978, prepared by the Hydrologic Engineering Center, U.S. Army Corps of Engineers, Davis, California, were used to develop the inflow hydrograph.
 - a. The 24-hour, 10-year and 100-year rainfall for the dam location were taken from the data for the rainfall station at Jefferson City, Missouri, as supplied by the St. Louis District, Corps of Engineers, per their letter dated 6 March 1979. The 24-hour probable maximum precipitation was taken from the curves of Hydrometeorological Report No. 33 and current Corps of Engineers and St. Louis District policy and guidance for hydraulics and hydrology.
 - b. Drainage area = 1.26 square miles (808 acres).
 - c. Time of concentration of runoff = 0.68 hours, as computed by the SCS Upland Method.
 - d. Antecedent moisture conditions for the probable maximum flood were assumed to be heavy rainfall and low temperatures for the previous five days (SCS AMC III). Antecedent moisture conditions for the 100-year flood were assumed to be an average of the conditions which have preceded the occurrence of the maximum annual flood on numerous watersheds (SCS AMC II).
 - e. Initial pool elevation was assumed to be at the riser crest (Elev. 802.2).
 - f. Total losses for the 24-hour 100-year storm were 2.11 inches. Total losses for the 24-hour PMP were 1.02 inches. The average loss rate for the 24-hour PMP was 0.04 inch per hour. Losses were determined using SCS CN 82 (AMC II) for the 24-hour, 100-year storm and SCS CN 92 (AMC III) for the PMP. Soils in the watershed are composed of approximately 14% SCS Soil Group B, 60% Soil Group C, and 26% Soil Group D. Land use in the watershed is approximately 50% cropland, 25% woods, and 25% pasture.
- The discharge rating curve for the principal spillway was determined using the following equations.

Full pipe flow:

$$Q = A\sqrt{\frac{2gH}{1 + K_p + K_b + K_pL}}, \text{ where}$$

A = cross sectional area of 30" diameter pipe = 4.91 ft^2 H = total head above © OF OUTLET, FT. K_e = entrance loss coefficient = 0.50 Kb= bend loss coefficient = 0.36 Kp= pipe friction loss coefficient = 0.00786 L = effective pipe length = 101 ft.

Weir flow:

 $Q = CLH^{3/2}$, where

C = weir coefficient = 3.1

L = weir length = circumference of 6' diameter riser = 18.85 ft.

H = total head above riser crest, ft.

Orifice flow:

 $Q = CA_r \sqrt{2gH}$, where

C = orifice coefficient = 0.6

Ar= cross sectional area of riser = 28.27 ft^2


H = total head above riser crest, ft.


Loss coefficients used in the full pipe flow equation were determined from the SCS National Engineering Handbook, Section 5, Hydraulics. Principal spillway discharges were controlled by weir flow over the riser crest for heads of 0.0 to 1.6 feet and by full flow in the 30-inch diameter pipe for heads greater than 1.6 feet.


The discharge rating for the emergency spillway was developed using the Corps of Engineers HEC-2 Water Surface Profiles computer program. The control section for the emergency spillway is approximately 50 feet downstream of the dam center line.

The discharge rating for flow over the dam crest, including levee extension at the left end of the dam, was developed using the option of the HEC-1 (Dam Safety Version) program for flow over a non-level dam crest.

3. Floods were routed through the reservoir using the HEC-1 (Dam Safety Verson) program. Input, output, and plotted hydrographs are included with this report.







\\	A1 MISSOURI DAM SAFETY INSPECTIONS A2 LAKE CHATEAU DAM MO 10015 A3 RATIOS UF PHF A3 DAM MO 10015 A3 DO00260000000000000000000000000000000000	!
	0000001.26 000024.8000013.000012 00000.41 0000001 0000000 0000000 0000000	
	Y 10 50 21 20 0 50 2 2 50 0 0 50 2 2 0 0 0 50 2 2 0 0 0 50 2 2 0 0 0 50 2 2 0 0 0 50 2 2 0 0 0 50 2 2 0 0 0 50 2 2 0 0 0 50 2 2 0 0 0 50 2 2 0 0 0 50 2 2 2 0 0 0 50 2 2 2 0 0 0 50 2 2 2 0 0 0 50 2 2 2 0 0 0 50 2 2 2 0 0 0 0	
Data Documents, inc	A A A A A A A A A A A A A A A A A A A	
<u>LELEN</u>		!
PLATE D		
-6		

e:

|--|

	1033		3
i	i	00.00	00.00
		0	0
10.00	0.00		00.0
		00.0	00.0 10.
		00.0	00.0
			00.0
ŀ	ŀ	00.0	00.0
		00.0	00.0
-	-	0010	00,0 10,
		30	00.
		00.	00.
		00.	.00
ļ	ļ	00.	00. 10.
		8.	00.
		38	100
		00	00.
		00.	00.
-	-	00.	000
		8.8	00.
		30.	
		00.	.00
		8,8	0. 0.
		8	00.
		00.	.01
		000	100
		30	10.
		10.	101 101
		10.	10.
		ē ē	10.
!	!	10.	10.
		10.	10.
		10.	101 101
		70.	10. 10.
			10.
1	1		100
		10.	10.
ļ	ļ	10.	10.
		10.	10.
ļ	ļ	10.	10. 10.
		10.	10. 10.
		10.	10.
İ	İ	5	10.
		ē ē	10.
		2	10.

28 2Wt '138

	•											1					:									•														1				
			!																							1									1					:				
										:		-		1					:					:		1									1					:				
10 17 17 17 17 17 17 17	3181.	55	77	Š	2605.	2441.	2388.	352	7 60	2.2	2182.	1758	1470.	8	934	586.	481.	403	34	269.	246.	229.	206.	199.	194.	187	185.	183	181.	181	<u>.</u>	191	181.	<u>.</u>		181	18:	101	181	191	181	181	181	191
1.00 1.00	÷.	9.	00	8	8	39	8	3.		00.	8	30	8	6	3	90	.00	9	3	38	00.	0.0	9 9	00.	8	96	8	8.0	9	8	9	38	8.	8	38	6	8	30	8	.03	50	8	3	2
	62:	• 23	629	.23	.23	. 23	.23	.23	57.	- 02	20.	20	.02	20.	200	70.	.02	20.	20.	70.	.02	.02	70.	.02	0.	20.	.02	70°	20.	-00	0.	70.	.02	.05	- 02	.02	70.	70.	.02	.02	70.	. 25	.02	70.
10 10 10 10 10 10 10 10	.30	•23	23.	.23	.23	. 23	.23	.23	57.	-02	-02	200	.02	0.00	20.	05	20.	-02	20.	20.	• 02	.02	700	.02	20.	20.	• 05	20.0	0.	.02	.02	.00	.02	20.5	70	.02	705	70.	.02	.02	70.	0.	.02	70.
5.00 10 10 10 10 10 10 10	204 205	206	202	209	210	212	213	214	212	217	218	220	221	222	223	225	226	227	228	230	231	232	234	235	236	238	239	240	242	243	244	549	247	248	250	152	252	254	255	256	758 758	528	260	197
10	17.00	17.10	17.20	17.25	17.30	17.40	17.45	17.50	14.00	18.05	18.10	16.20	18.25	18.30	18.35	18.45	18.50	18.55	00.00	19.10	19.15	19.20	19.30	19.35	19.40	19.50	19.55	20.00	20.10	20.15	20.20	20.30	20.35	20.40	20.50	20.55	21.00	21.10	21.15	21.20	21.45	21.35	21.40	21.45
\$ 5.00	1.01	5.1	5.5	5	5	10.	.0	1.01	5 5	1:01	7.0	50	1.0	70.	55	10.1	1.01	10.1	10:1	10.1	1.01	3.5	10.7	10.1	5	10.1	1.01	100	1.0	1.01	5.0	5 5	1.01	10.1	10.1	1.01	5.0	5 5	1.0	10.1	10.1	:0:	5.1	10:1
\$ 5.00	•			: .:	•	•		•	-		.		: -:		.	: .		•	•	• •	•		•		٠.			25		-	.	• •	5.	.		:	•	• -	: :			7.		•
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	~ ~	~		~	Ž.	~ ~	~		6 a		2:	-	23:	28	<u> </u>	9	3	46	9	2 0	2	52	U 10	150	30	26	36	57	2	58	90	200	29	50	59	25	50	2 6	9	09	9 6	20	9	2
\$ 5.00	88	8	88	8	8	96	8	0	8 8	.02	70.	70	ē.		<u>.</u>	5	10.	0.	5.0	3 5	5		16	10.	5.	10	.0	5	6	8	e e	33	00.	8.8	00	8	8	30	8	88	30	20	00	3.
	9.9	0	5	ē	0.	ē ē	ē ē	5	<u>.</u>	.00	50.	ç č	9	•05	ė,	5.6	90.	90.	9	ŝ	90.	90.	9 6	90.	90.	90	9	90.	ó	9	33	90	90.	9.0	90	90.	90.	9 6	9	.00	5 6	90	90.	ŝ
	5.5	5	5	; ē	9	5	: 5	6.	ē		-0.	5 6	6	-07	6.5	5 6	10.	10.	6	3 6	.0	10.	9 6	10.	20.	00	.0	0.0	6	.0	6.6	50	.01	6.5	0	.0.	6	9 6	0.	6	50	.0	.00	?
	94	3	6	\$	9	79	5	2	= 2	===	2)	2,2	==	2	2 3	2 =	82	83	5	6 49 60 60 60 60 60 60 60 60 60 60 60 60 60	97	80		16	76	96	\$	96		66	2 :	102	103	707	136	107	901	2 -	=	112		2:	116	Ξ
	5.00	2.10	5	5.25	5.30	 	5.45	5.50	2.5	6.35	01.9	2.5	6.25	6.30	6.35	9 4	6.50	6.55	00.	5.10	7.15	7.20	7.30	7.35	7.40	250	7.55	00.0	. 10	8.15	8.20	6.30	6.35	6.40	6.50	8.55	00.4	6.10	9.15	9:50	4.63	9.35	6.40	7.42
	0.0	0	916	9	0	n c	9	0	9.	OK	0	310	0	9	9	7	0	9	919	9	9	0	9	0	0.	9 0	0	00		• 1	•		•	•	• • •	•	٠	• •		•	5.5		•	-0:

		•											:	:	:							r		:			
	101		:::		3		- 101	: =	.101	= :		=		303363. 8590.281				:				1		:			
	88	8	36	3.6	8	9	3 6	36	8	9	88	8	60	1.02					!				i			;	
222	200	0.0	70	200	0.	2.5	200	70.	-02	20.	0.0	-02	20.	31.22													
2000	000	70.0		0.0	-02	0.0	> c	70.	O	0	20	.02	20.	32.24	JAE		2	2089.		-	:	1		! ! !			
267 268 268 269	270	272	274	275	277	278	200	281	282	203	285	286	280	SUS	Y.	3032	E .	28			1	;	:			1	
01 22.15 01 22.20 01 22.20	100	- Mile	4 74 1		• ~	i I	•	4 14	~		1	-	7		-HOUR TO	1053. 30.	31.10	2089. 2576-					:			1 1 1	
			:	-6	: = .	•	-	: -	-	. .		-			4-HOUR 72		0 0	2576.					:			:	
615.															7	3349. 95.	24.73	1661.			;				•		
						-									PEAK	9929. 281.			1				:				
000	6 6	0.0	200	000	0	0.	•	• •	.07	6.5	20.	٥.	0.0			S S	INCHES	AC-FT					!		; ;	į	
52 52 52 52 52 52 52 52 52 52 52 52 52 5	126	120	130	131	133	134	5 2	137	138	139		142	143					THOUS				<u> </u> 	1		;		
10.20	10.30	0.0	i i	o -	: ::	٠,	: -	::	-	: .	::-	-	-12	;			:				;			1			
5000	200	0.0	; 0	9,5	• •	•	•	::		o.	90	•	• •	1					!					1		1	
		:									:			:	1		1		!							; (

PEAK 6-HGUR 24-HGUR 72-HGUR 1074L 993. 335. 105. 105. 2.47 2.47 3.11 62.81 78.91 18.99 205. 259. 259. 259. 259. 259. 259. 259. 25																		٠			:								
25.5	2 %	3.11	78.99	258.	2	ł	1718.	6.22	157.98	515.		TOTAL VOLUME	106150.	3006	276.47	902.		•	1 .	151643.	15.55	394.95	1044.	1288.		VOLUM:	5582.	20.21	77 679
25.5	1	3.11	78.99	250.	LAN 1. RTEG	72-HOUR		6.22	157.98	515.	LAN 1, RT10	72-HOUR	369.	101	276.47	731.	1	LAN I. RTIG	72-HDUR	527.	15.55	394,95	1055.	1288.	LAN 1, RT10	12-HUUR	61	20.21	47 613
25.5	24-HDUR 105.	3.1	78.99	258.	10001 FOR P	24-HOUR	•••	6.22	157.98	515.	00001 FOR P	24-HOUR	369.	01 07	276.47	131.	· · · · · · · · · · · · · · · · · · ·	10001 FOR P	24-HOUR	527.	15.55	394.95	1044:	1288.		24-HOUR	19.	20.21	517.66
25.5	6-HOUR 335.	2.47	164.81	205.	H AF SFADO	6-HOUR		4.95	125.61	·014	H AT STADG	6-HOUR	1172.	33.	219.83	717.	:	H AT STADO	6-HOUR	1675.	12.36	314.04	430.	1024.	I AF STADO	6-HOUR	62.	16.07	36 007
CFS CFS INCHES	PEAK 993.	• 69			HYDROGRAP	PEAK	26.				HYDROGRAPI	PEAK	3475.	68				HYDROCRAPI	PEAK	4965	176.				HYDROGRAPI	PEAK	183.		
	CFS	INCHES	٠,	THOUS CU M		300	SS	INCHES	E S	THOUS CO M			CFS	CACHE	I	THOUS CU M				25	INCHES	Ŧ	1131	3	:	393	SES	INCHES	22

SELA CONCUMENTAL LINE: 02

											·		ı	•		808.00	1560.00					
) : !			807.00	750.00		:	i		
													IAUTO			806.00	280.00					
	VOLUME 42629.	5870.	11.92	1671. 2061.		VOLUME	1286.	11.10	9.90	2089.			NAME ISTAGE	LSTR	IRA ISPRAT	805.00	8				EXPL 0.0	
R710 6	TOTA			, ,	RT10 7	TOTAL	1				•	***	PRI	0 th	TSK STURA 0.000 -802.	2	122.00		1		O CAREA	DAMHID
PLAN 1. B	,~	!	1	1671.	PLAN 12		ţ		- {	2576.		DUTING CHATEAU		10PT 0	× 000		121.00			1	ELEVL COOL	DAM DATA
STA000001 FUR	24-HOUR 842.	24.	631.92	1671.	STA000001 FOR	24-HOUR	1053.	31.10	789.90	2576.	•	APH A	I V	ROUTING DATI	AMSKK 0.000	90		139,	2113.	830.	EXPH ELE	٠.
¥	6-HOUR 2679.	76.	502.46	1329.	¥	6-HOUR	3349.	24.73	628.07	2049.	•	HYDROGRAPHS	I EC	=	L LAG	803.	97. 00	83.	1014.	820.		TOPEL
HYDROGRAPH	PEAK 7944.	225.			HYDROGRAPH	PEAK	9929	.107			•	NG OF	2	\$5 AVG	PS NSTDL 1 0	803.00	42.00	37.	430	.010	SPW10	,
_	CF.S	CAS	I	AC-FT DUS CU M			CFS	INCHES	I		•	TIME STONES	_	0.0 0.000 0.0 0.000	NSTPS	802.50 810.00	10.00	25.	183.	802.	CREL 802.2	; ;
			i	1HO						1HO	•	3.0				802.20	2630.00	AREA. 0.	117.	10N= 780.		:
		<u> </u>									:		:	; - - 1	1	STAGE	FLOW	SURFACE AF	CAPACITY	ELEVATION=		-

The second secon

	:																								:																						
			••	0.	ġ.				-	13.	20.	32	36.	43.	73.	110.	171	524.	320.	240.	140.	123.	122.	110.	97.			188.	100.	188.		180	190.	191.	194.	197.	200	203	207.	209.	210.	.822	239.	260.	27.7	264.	256.
		!	. .	.0	.	<u>.</u>	2.	· "	7.	12.	. 6	70.	36.	42.	.69	106.	129	263	332.	247.	146.	123.	122.	113.	68			188.	188.	. 88		5	190.	191.	194.	197.	.00	202	207.	209.	217.	227.	238.	255.		264.	257.
0.01				•0	•	: -	2.	i #	•	-1-	. 61		36.	40*	.99	102.	121	200	345	254.	153.	123.	123.	116.	92.	16.	:	168.	188.	188.		80	190.	190.	193.	196.		202	206.	208.	216.	226.	236.	251.	27.2	265.	258.
807.6	END-OF-PERIOD HYDROGRAPH ORDINATES	; ;	.	0	å.	: -	2.	, e	•	10.		626	300	+0+	63.	96.	152	• • • • • • • • • • • • • • • • • • • •	359.	259.	162.	123.	123.	-611	96	11.		188.	186.	188.	691		190	190.	193.	196.	5.00	206	206.	208.	215.	225.	235.	248.	210.	265.	259.
807.5	HYDROGRAPH	i		İ		<u>:</u> -					17.			- 1			•			i		- 1			i i		AGE		188.	. 661		180	190.	190	193.	.961	661	206.	206.	208.	214.	224.	234.	247.	0.70	265.	260.
807.2 80 STATION 000002.	-0F-PER 100	OUTFLO	••	- 0,	Ġ		2.	2.	2	.6	.91	200	34.	39.	57.	- 26 -	121	642	390.	272.	183.	123.	123.	121	96	.08	STORAG		188.	188		180	190	190	192.	195.		707	206.	208.	213.	223.	233.	245.	2,00	265.	261.
1.908	END		. .	.0	•	<i>-</i> -	2.	. ~	5.	•	9:	16.5	34.	38.	54.		121	6009	•10. •10.	279.	195.	124.	123.	121.	101	.18		188.	188.	. 881		180	190•	190.	192.	195.	- C	204	206.	207.	213.	222.	232.	244.		266.	261.
1.60		1	••			<u>:</u> -	2:	2	•		15.	286	33.	38	51.	. 95	122	513	433.	266.	207.	126.	123.	121.	103.	93.		188.	168.	186.	189	189	190	190	192.	195.	961	203	205	207.	217.	221.	231.	243.	271	266.	262.
•			• •	•	ė.	: -		. 2	•	8	: ;	216	33.	37.	48.	6.	123	. 771	461.	298.	220.	130.	123.	122.	105.	84.		188.	186.	188.		180	189.	190	191.	194.	200	203	205	207.	211.	220.	230.	241.	271	266.	263.
ברבגאו ומי		i i i	• •	0.	ċ	.			-			27.	32.	37.	*94	. %.	100	• 751	492	308.	.162	900	123.	122.	108.	96.		188.	199		* 00 0		*691	061	191.	. 194.			205	207.	210.	219.	223.	243.	- 607	267.	264.

Dete Documents, Inc. 42


PLATE D-13

-

>																								•			,							,		
									:					:										!												
;							ı							:													:									
		i								-	. :					-			· •					:	:						!					
253. 251. 249.			802.2	802.2	802.3	802.3	802.5	602.7	903.2	804.7	904.6	804.9	100	805.6	805.8	905.9	806.7	900	805.7	605.1	904.0	100	804.5	\$04.4									1	:		į
53.	} :	i	7.	: ~		w.	-	•	7	-	~	6	۰				٠, í	(0)		-		•		.5			.									
2 2 2 2			802.2	802	602	802	802	805	903		400	804	809	808	805	608	908	900	605	802	100		900	904	1						!			1		
253.	247.	!	802.2	802.2	802.3	802.3	602.5	802.6	A03.1	805.0	604.5	804.9	805.0	805.6	805.8	805.9	806.2	80.0	805.6	805.2	809-9	404	804.5	804.5				143152.	\$05¢	14.68	986	1216.		!		,
4.4			~;	: ~		ų.	-	. •	9	و ۾		•	e -				·			~	9	-			•			1	:							,
251.	**	1	802.2	802	905	208	802	802	603		909	804	805.0	808	808	902	908		805	605	61.506		90	0	5			497.	15	9 9	190	.91	,			;
254.	247.	1	102.2	205.2	302.2	302-3	102.5	302.5	903.0	0.00	104.4	904.8	0.00	105.5	105.7	105.9	0.90	0.00	105.8	305.3	204.9	400	9.0	804.5				4	1	37.5		21				
• • •		AGE_									ļ																	497.	151	9 6	906	-		:		
255	247	•	802.2	802	802.	602	802	805.	905	803	904	904	600	805.	805.	805	908	90	805	805	9051		804	804			19	5 -	7.							
254. 252. 250.	248.		802.2	2.2	32.2	52.3	12.4	2.5	22.9	•	5.3	8.40	5.0	25.4	25.7	25.6	0.50		805.8	15.4	904.9		9.4	5.4.2	;	v		1661.	•	311.	95	5		:		
		1	ĕ ₹	ă		3 3	į	.	5	Ď Œ	6	ā	.	8	ă	•	ă ă	ŏĕ		ĕ	6	Ďà	Š		• .	OB HOUR	74 54	4703.	133.					1		
255.	248.	:	802.2	802.2	802.2	802.3	802.4	802.5	802.0	808	809.3	804.7	0.00	605.4	805.7	802.8	806.0	806	805.8	805.5	905.0	409	804.6	804.5	֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓	•		v	<u>.</u>	v z		x		:		
255. 253. 250.	.01		~.	. ~ .	2.2	۳.	7.7		6.5	٠.	7	ا د .	0 -	2.3	2.1	97	0 -			9.0	0.			5.40	. 1	AT TIME		5	3	INCHES	•	THOUS CO	1			1
. ii ii ii	Ň	1	805		0	2		0	Ce	2 6	8	8	805.0	200	9	2	6	è	60	9	905.0	9 6	Š	000	•	4703. 1					1	Ξ				:
253.	248.	i	802.2	602.2	802.2	602.3	802.4	802.5	802.7	200	805.2	904.6	805.0	805.3	835.6	805.8	605.0	200	805.9	805.7	905.0	904.0	804.6	804.5		s	-		,		:					
	1	i					1		-					!							;			i i		OUTFLON I	1							1		
	: (;								1		,			!		:			1		1			;		PEAK UU	-				:					
	!				ļ		:		ı L					1		•			į							٠.	į				1			;		i

2000. 3000. 4000. 5000. 0. STAT 10M000002 PLATE D-16

Deta Detumpett, Inc. 91



• • • •				•	• • •			•					•		• •			• :	• •		•	•		. : •	•	• •	•			; •
• • • •	• • •					: ! • • •	•				• •	;							• •		•	: - -				• •				
• • • •	!														-		:	1.022220			•									
			*********															********						•			-			
		1		!					!					•		• •			•		•	1	•		-	• •		. •		
• • •					• • •		;			•	•	•		••		• •	# • • :	3 4 5 5 6 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	• •	•	• •	•	•			• •		• •	!	
• • • •			***************************************		• • •					•	• •	•		••		• •	• •	\$5 7 % 5 6 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	• •	•	• (•	• •:		•	• •		• •	• •	
• • • •					• • •	•••			••	•••	• •	•		••	-	• •			• •	•	•	•	•		•	• •		•	•	
	•••		. 0	10	,	••			••	•	• •	•		••	•	• •	•		• •	•	•	•	• •		•	• •	•	•		
•••	•••		•		_°	0			••	•	•	•		• •	•	• •	• •	******	• •	•	• •	•	• •	•		• •	•	• (
• • • •		0				••	0		••	•	• •	•		• •	•	• •	••	********	• •	•	• •	•	•		•			•		
	50°		•	•	• •	• •		_	اء ۱	90	• • •			20:	•	• •	• •		• •	•	• •	٠	• •		•	• •	•	• •	•	
•••	.				• • •	• •		•	••	•	•	•		• •	-	- 5	0 0	وأديميه	_		 • .		0			• •		• •	•	
5.05181. 5.10182. 5.15183.	15.25105.	15.40188.	2,20190 5,55191. 6,00192.	16.10194.	6.15195.	16.25197.	16.46200	6.45201.	16.55203.	7.10206.	7.15207.	.25209.	1.35211.	7.45213.	.55215.	8.00214.	8.10218. 8.15219.	18.2022011	8.30222.	8.40224.	8.50226. 1	18.55227.	-	19.10230.1.	19.20232.1 U	. 30234 . 10	7.32235.1U 9.40236.10	9.45237.10	19.55239.10	20.05241.10

DPEBATION SI HYDROGRAPH AT C RDUTED TO C	100000	-										
H AI	100000	AREA	PLAN RA		RATIO 2 R	ATIOS APP	RATIOS APPLIED TO FLOMS	5	BATIO 6	AATIO 7		:
i 1 ! !	100000			2	-20	.35	.50	.65	•	00.1		
		1.26		993.	1986.	3475.	4965.	6454.	7944.	9929.	1	
	000002	1.26		648.	1732.	3186.	4703.	6227.	219.20)(277.3411		
								!				i
												, , ,
											:	•
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1												
											The state of the s	! !
i												:
												1 1
								!				ļ ļ
												: :
			 			! !						
The state of the s									 		· !	: : :
			:	:								
					! !							

...

1 1 1

:				:		£ 7 1			
	TIME OF FAILURE HOURS	000000	00.0						
0F DAM 804.60 253. 123.	TIME OF MAX GUIFLOW HOURS	16.3 16.0 16.0 16.0 16.0 16.0 16.0	16.00						
0	DURATION DVER TOP HOURS	M 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	16.17						
SPILLMAY CREST 802.20 188. 0.	MAXIMUM DUTFLOW CFS	6+8. 13-2. 31-82. 470-8. 622-7.	9794.						
INITIAL VALUE 602.20 108. 0.	NAXI MUN STORAGE AC-FT	276. 297. 315. 330. 350.	361.			-			
	MAXIMUM DEPTH OVER DAM	2.55 2.55 2.55 2.55 4.15	3.45						
ELEVATION STORAGE DUTFLOW	MAXIMUM RESERVOIR N.S.ELEV	805,39 806,67 806,67 807,67	808.05						
	RATIO OF PMF	2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	1.00						
PLAN 1						; ;	! !	! j ! ! !	1
				•					i

THE CANADACTION CONTRICTORY CORPORATION CONTRICTORY	A 10 YEAR 11000 B 0402864000000000000000000000000000000000	
0 000.00	1000003 C0000001 CALCHIATION OF 10-YB, FLOOD HYDBREAPH	
1110-1014/201000-1014/201000-1014/2010-1014/2010-10	000000020001.24	
1100 . Oristone, additione, designed, additione, addi	M M	
1100 0.0151004 0.0550004 0.0550004 0.0550004 0.0550000 0.0550000 0.0550000 0.0550000 0.0550000 0.0550000 0.0550000 0.0550000 0.0550000 0.0550000 0.0550000 0.0550000 0.0550000 0.0550000 0.0550000 0.0550000 0.0550000 0.055000 0.	0100.0050000.005000 0.0050000.0050000.0050000.0050000.0050000.0050000.0050000.005	
India Cristage C	0100.001500001.0050000.0050000.0050000.0050000.0050000.0050000.0050000.0050000.005	1
100 - 11 100 10 100 10 100 10 100 10 100 10 100 10 100 10 100 10 100 10 100 10 100 10 100 10	1110.0050000.0050000.0050000.0050000.0050000.0050000.0050000.0050000.0050000.0050000.0050000.00500000.00500000.00500000.00500000.00500000.00500000.00500000.00500000.00500000.00500000.00500000.00500000.00500000.00500000.005000000	
1010 0.11100000_11100000_1110000_11100000_11100000_11100000_11100000_11100000_11100000_111000000	~ ~	
100 0.1150000.1150000.1150000.1150000.1150000.1150000.1150000.015000.015000.01500000.0150000.01500000.01500000.01500000.01500000.01500000.01500000.01500000.0150000.0150000.0150000.0150000.0150000.01500000.01500000.0150000.0150000.0150000.0150000.0150000.0150000.0150000.015000000.0150000.0150000.0150000.0150000.0150000.0150000.0150000.0150000.0150000.0150000.0150000.0150000.0150000.0150000.0150000.01500000.0150000.0150000.0150000.01500000000		
1100.0.1900000.13000000.13000000.3900000.3900000.1500000.01990000.0199000.019990000.01999000.01999000.019990000.01999000.01999000.01999000.01999000.01999000.019990000.019990000.019990000.019990000.019990000.0		
100 0.12 9000 0.12 9000 0.13 9000 0.13 9000 0.13 9000 0.12 9000 0.12 9000 0.12 9000 0.12 9000 0.12 9000 0.12 9000 0.12 9000 0.13 9000		1
1000 0.1530000. 0.1530000. 1150000. 1150000. 1150000. 0.150000.		
100 0.01 10000.0000.01 10000.01 10000.01 10000.01 10000.01 10000.01 10000.01 10000.01 10000.01 10000.01 10000.01 10000.01 10000.01 10000.01 10000		
1010.0.110000.0110000.0110000.01110000.01110000.01100000.0110000.0110000.0110000.0110000.0110000.0110000.0110000.0100000.001000.001000.001000.001000.001000.001000.001000.001000.001000.001000.001000.001000.001000.001000.0010000.001000.001000.001000.001000.001000.001000.001000.001000.0010000.001000.001000.001000.001000.001000.001000.001000.001000.0010000.001000.001000.001000.001000.001000.001000.001000.001000.0010000.001000.001000.001000.001000.001000.001000.001000.001000.0010000.0010000.0010000.0010000.0010000.0010000.0010000.0010000.0010000.001000.001000.001000.001000.001000.001000.001000.001000.0010000.001000.001000.001000.001000.001000.001000.001000.001000.0010000.001000.001000.001000.001000.001000.001000.001000.001000.001000.001000.001000.001000.001000.00100.001000.001000.001000.001000.001000.001000.00100.001000.001000.001000.00100.00100.00100.001000.00100.00100.00100.00100.00100.00100.00100.00100.00100.001000.00100.00100.00100.00100.00100.00100.00100.00100.00100.00100.001000.00100.00100.00100.00100.00100.00100.00100.00100.00100.001000.00100		
1000050000.0050000.0050000.0050000.0050000.0050000.005000.005000.005000.005000.005000.005000.005000.005000.005000.005000.0050000.005000.005000.005000.005000.005000.005000.005000.005000.0050000.005000.005000.005000.005000.005000.005000.005000.005000.00550000.005500.005500	==	
11 dt., d0.300001, d0.500001, d0.500001, d0.500001, d0.500001, d0.50001, d	0100,0050000,0050000,0050000,0050000,005000,005000,005000,005000,005000,005	
01100.0059000.0050000.0050000.00550000.0055000.0055000.00550000.0055000.0055000.0055000.0055000.0055000.0055000.0055000.0055000.00550000.00550000.00550000.005500.0055		
DIRO, . DESGROOD	0100.0050000.005000 0.0050000.0050000.0050000.0050000.0050000.0050000.0050000.0050000.005 0100.0050000.005000 0.0 050000.0050000.0050000.0050000.0050000.0050000.0050000.0050000.005	
11.	0100.0050000.0050000.0050000.0050000.0050000.0050000.0050000.0050000.0050000.0050000.005	
x u00000. x u RESERVDIA ROUITING DE 10-YR. CLUGO y a0000001 x u0000101000002 x u 0000001 y 1000001 y 40802. 20000010. 0000002. 5000002. 50000000. 2. 00000000. 2. 00000000. 2. 00000001. 0000001. 00000001. 0000000. 000001. 00000000	T -82.	
Y1000uu1 Y100uu1 Y10uu1	00000010000001. 0000010000002 0 RESERVIJE ROUTING DE 10-YR. FLOGO	
140802.2000802.5000802.5000803.5000803.6000023.6000804.0000804.0000807.000807.000804. 14008040.000810.0000042.4000087.0000121.0000122.0000124.0000280.0001560. 1502631.000440. 1502631.000440. 150000.00000025.0000810.0000820.0000830. 150000.000000025.0000810.0000802.00008007.8000801.00001125. 150010.0000085.0000400.000080.0000807.8000807.8000810.	000000	
Y 5 CCOOC, CCOCOLO. UCCOCO 4. CCOCOLO 1. CCCCC 2. CCCCC 80. CCCC 80. CCCCC C 80. CCCCC C 80. CCCCC CC 80. CCCCCC 80. CCCCCC 80. CCCCCCCCCC	0000603.000803.	
\$40000.000025.0000037.0000030. \$160780.0000802.0000810.0000820. \$100780.0000001.50001125. \$100110.0000285.0000400.0000780.0001100.0001125. \$100110.0000285.0000400.0000780.0000100.0001125. \$10010.0000285.1000804.100804.200807.500807.8000810.	0000042+0000081	
\$10010. \$000003. \$00011.55. \$1 00110. 00002.85. 0000400.0000 780. 00001100. 0001125. \$1 0010.95. \$2 0000400.0000 780. 00007807. \$0000807. \$0000810. \$1 0010.95. \$2 0000400.0000 780. 00001100. 0001125.	\$4,00000 . 0000025 . 0000037 . 0000083 . 00000139 .	
* VOBO 99 * COURS OF LOOP BUT - ZUOU BUT - BUUU COBLU - BUUU - BUUU COBLU - BUUU COBLU - BUUU COBLU - BUUU COBLU - BUUU COBLU - BUUU COBLU - BUUU COBLU - BUUU COBLU - BUUU COBLU - BUUU COBLU - BUUU COBLU - BUUU COBLU - BUUU COBLU - BUUU COBLU - BUUU COBUU - BUUU COBLU - BUUU COBLU - BUUU COBLU - BUUU COBLU - BUUU COBLU - BUUU COBLU - BUUU COBLU - BUUU COBLU - BUUU COBLU - BUUU CO	\$ 200 HO 4 6 600 600 1 500 60 1 1 2 5 . \$ 100 60 5 60 60 1 1 2 5 . \$ 10 60 1 1 0 5 60 60 5 60 60 60 60 60 60 60 60 60 60 60 60 60	; ; ; ;
	870809-4-6000805-1000806-100080	: :
		i :

LAST MOLEICAIDE 26 FEB 25				
DATE= 19/11/15. TIME= 15.00.47.				:
MISSOURI DAM SAFETY INSPECTIONS LAKE CHATEALI DAM MO 10015 10-YEAR FLOOD	S			
NG NHR WHIN IDAY IHR	3	IPLT IPRE	NSTAM .	
-	LROPT TRACE			1
***	******	******	********	
SUB-AREA RUNDEF CO	NOFF COMPUTATION			
•	ITAPE JPLT 0 2	JPRT INAME 0 I	ISTAGE IAUTO	
TABEA	DA 7A		W	
2 1.26 0.00	1.00 0.000	0		
NP SIGN 288 0.00 288 0.00	STORM DAJ DAK 0.00 0.00 0.00			
10. 10. 10.	-		10.	
10, 10, 10,			101	!
10. 10.				
10. 10. 10.	10. 10.	10.	10.	
10. 10. 10.				
10. 10.			10.	
20. 20. 20.			.02	
20. 20. 20.			50.	
15 15		!	80.	:
20.			505	
202 402 802 02 01 01	1	;	0.01	
10. 10.			5	
161 161	111111	1	io.	

	:																			:		1				: :			
	-							CUMP Q	615.	1184.	1466.	1637.	1370.	1177.	985	710.	582	521.	464.	369.	331.	266.	237.	189.	171	150.	144.	136.	134.
2000	50.					.00	25.	5501	*!	.00	<u>.</u>	100		100	55	00.	00.	8	8.8	8	8.6	00.	8 5	8	8 8	00.	86	8	80
0000	20.	0.00				VOL - 1.	33.	EXCS	.45	.12	.0. 70.	200		500	50.	20.	20.	.03	60.	10.	.	10.	10.	50	.	0.	10.0	10.	5.0
0000	100	AL SMX 0.00				.43	- N	RAIN	.59	. 15	80. 80.	900		90.	88	.03	.03	.03	6.0	.02	70.0	70.	70.	.02	20.0	20.	.02	- 05	70.
		CNST1			00.1	S, LAG=		PER 100	145	14	148	150	151	153	155	157	158	160	161	163	164	166	167	691	170	172	173	175	176
50000	555	SIRIL -1.00	82.00		RT IOR.	.00 HOUR	.09	HR. MN	12.05	12.15	12.20	12.30	12.40	12.45	12.55	13.05	13.10	13.20	13.25	13.35	13.40	13.50	13.55	14.05	14.10	14.20	14.25	14.35	14.40
5555	555	1.00 1.00	ECT CN =	1 DATA	DA1A 01	0	91.	FL OW MO.DA	1.01		1.01	1.01	56	1001	100		1.0	10.1	10.1	1.01	5 .5	1.01	0.0	1.0	- - -		5.0	1.01	
5555	100	1055 DATA 518K S 0.00	빏	HYDROGRAPH LAG=	RECESSION DA	•	110.	END-OF-PERIOD COMP Q				0.	• •	000	: .			0.	o d	0.	•	0					•		• •
10000		ERAIN 0.00	-1.00	0.00	9.00 QF	8	1	END-OF																		; 			
		RT 10L	HE THESS	-51		9	149.	108	.									ĺ		ĺ									5.5
9999	555	OLIKR A	-62.00		STRTG	1 27 END	199.	I EXCS	1											}						į		!	0.00
0000	555	SIRKE D	모			IDROGRAPH	273.	DO RAIN		9	0.0	00 0	•			1						-							32 5E
====		LROPI	CURVE			TIMI.		N PER100	80.0	, I	20	0	n 0			1	O #		.	2	۰.	: :	.		o 4	-	10 C		0 m
00000	999	81				120	363	DA HR.MN		•			• •		· · .]			~ -			"-	~ ^	7	~ ~	7	~ ~		2.4
	1							¥0.	13.	-	9.0	74	::)-[1				-		-			
	; ;					• = •	ļ.,		<u> </u>	!					-, -				. ,	ļ		:		j,				<u> </u>	 -

The colours of the second second second second second second second second second second second second second

<u></u>	>		=	- -		<u>-</u>	-	·	=		=	=	-	=	•	i i	.~ == .	Ī				(? 2	-			<u>-</u>	-		•	-	<u>.</u>	-	Ī	1 7 1 7	1	<u>.</u>					I			1	•	1	=
					: : : : : : : : : : : : : : : : : : : :																																							!			
; ;	;;	44.	•	•	44	***	44.	46.	*	44.	**	+ + -	666	•		44	**	•		;	. 44.	;;	46.	; ;	*	;	; ;	*	44.	450	•	; ;	44.	*			;	. 44	*	32067.	10000						
38	00.	.00	8	3 5	00	0	00	00.	8.	• 00	8	8	8	3	38	00.	8	8	9 6	38	8	9	•00	88	8	8:	88	8	8	88	8.8	38	8	• 00	8	3		8	9	1,95							
38	00.	00.	Ş	9 5	000	00	0	00.	00.	000	0.	0	8	9.0	38	8	00.	9	3 6	3	0	8	00.	8 5	00	8	9 6	8	00.	00	000	9 6	9.	8	8	3	88	0	8.	3.3							
10. 242 242 .01																		1												-										SUM 5.26	- 134	VOL UME	32038.	3.29	83.44	2213	.212
																																								ns		TOTAL	m	-			
.01 20.05					!_			_	_	_!	_	_	_ .			1_	_	⅃.			!_	_	_].			_		_	_	ļ			1_	_	-				. .			72-HOUR	::	3.29	83.44	221.	212
	_	1	_	-				-	-	7	_	_			-		~		-	-				-		·			~	-	~ •			-	-		• -	_	-			-HOUR	:: :-	3.29	83.44	2214	717
12:	13.	14.	5:	9 3	1 7	91	19.	20.	20.	210	22.	24.	26.	-87	33.	35.	36.	30		42.	=	45.	46.	-	5	53.		75.	ż	350	. 201	148.	134	201.	250.		310.	365.	451.	-		2		99		100	22.
. .	5.	10.	5.	5.5	10.		10.	10.	10.	10.	10.	10.	10:	5		5	10.	100	.		5	ō.	100	6.	. 20	20.	20.	20.	.02	600	6.0	5 6		.03	8	5.0	5	50.	=	!		9			•		
38										1																				1												PEAK	_	P!			
10. 10.										- [1								CFS SES	INCHES	Ŧ	AC-EI	THOUS CU M
]	_	_		_	7	_	_	7	-			_]	-	_		_				_	_]	_]		_		_]		• -	-	_								Ξ
01.8 10.		ĺ			1			1		-			-					-	_		1	_	7					7-	_	1		10.	٦,	_	-			-	_			!		:		-	
	: _	**	-	- -		-	-		-	1.	-	<u>-</u>	•	∴ .	:		=	•	<u>:</u> .			-	4	-: -		:	<u>-</u>	==		-	: -	<u></u>	-	:	-	: -	: -	-	÷	:						1	
	C		Ξ	-		_	<u>-</u>	 -	-					-	_	i -					-			<u></u>	÷		. 7	Ļ					_	•					:-:			<u> </u>	22	! !-	<u> </u>	-	_

-...-₁

i

				1																																												
2.22.22.22.22.22.22.22.22.22.22.22.22.2	02.2 02.2	2.20	02.2	02.2	02.2	02.2	02.2	02.2	02.2	02.2	2.20	02.2	02.2	02.2	02.2	02.2	02.2	02.2	2.20	02.2	2.50	02.2	02.2	02.2	02.2	02.2	02.2	02.2	02.2	2.20	2,20	02.2	22.20	02.2	02+2	2.20	2.50	02.2	2.20	2 2 20	7.20	02.2	02.2	02.2	02.2	02.2	02.2	
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2				İ																											, the same of the		İ															
1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1		81	-	91	= :	= =	9	=	18	= :		191	=		-	-	18	-		= :		101	2	9			8	2 -	2	=			18	-	. 1	E :	2 4	18	8		-	2	•	=:	9	= <		:
2		9	ėė	0	•	.	6		ŏ	.	ė		•	6	.	ė	ė	•	3	•	.	•	•	9	•	; 6	0	•	0	•	å	: :	9	o d	•	•	.	0	ö	de	ė	ó	ö	•	9	ċċ	•	i c
		0		0	•	.			å	•	åá		ં	9	•	.		.	0.	ċ	;		ò	0	.	<i>:</i>	Ö	.		•		: :	9.	.	0	•	• e		.	ð	id	:	•	.	0	ő		; ;
		15	8 6 6 6	00	90	<u>-</u> '	33	7	50		2	63	92	00	8:		33	.42	20	B .		93	. 26	00	8:	25	33	2 5	58	19	22	92	00	9 ~	25	e 6	7	58	29	12		8		~:	25	33	20	2 4
		-		- 1			1		-										1			ı		-			ĺ						İ	•	- {					-			!		ļ			;
	2 % Q	55	o r	00	SO	2 5	20	22	30	35	.	50	32	8	£ .	2 2	20	52	2	32	2 ¥	50	22	00	S •	2 2	20	5 C	35	9	22	32	00	5 0	2	20	۲, E	35	9	45	2 5	8	03	2:	512	2 50	30	2 1
		-							ł			1					ŀ		1			1	_		- -	-	_	~ -		_	╛.					_	-	-	_	j.					╛.			i i -
		-	-	1	≟.			: 3	7	≟:			=	7	≟.			-	1	<u>.</u>	-		-	-	-		1.0	-		-		::	٦		-	-			7				-	-	7			
																																					•											•
				Ì										.															1				1															
				:																																												
			٠		÷				-	L	ئىـــــ		1	ı I		<u> </u>	Ļ	_	!	_			_			-	<u> </u>			T.,		_		1			_		_					1 7		2-2		•

€· PLATE D-30

		**		****							***					*																														
\$03.C	603.1 603.2	803.4	803.6	804.3	804.7	805.0	7.000		605.5	605.5	605.5	800.0	5000 5000 4.40	605.4	805.3	602.3	805.2	605.2	805.2	605.1	6024	805.0	805.0	005.0	805.0 805.0	804.9	. 404.9	804.9	804.9	804.9	9. 400	804.9	804.8	904.0	50 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	7.408	804.7	804.7	804.7	804.7	604.7	#04 · 7	804.7	804.7	804.6	9.400
208	215.	219.	226.	244:	254.	265	211.	2.79	260.	280.	260.	279.	277.	276.	275.	200	271.	270.	269.	268.	1797	266.	2654	264.	263.	262.	262.	261:	.192	2000	260.	259.	259.	258	258.	257.	257.	257.	256.	256.	256	255	255.	255.	254.	254
	52.	77.	102.	123.	127.	2412		773.	820.	825.	\$00		684.	636.	587	29.65	456.	410.	384.	353.	328.	276.	2561	241.	219.	210.	202.	189.	184.	188	170	167.	159.	156.	152.	146.	144.	141.	137	135.	133	136.	129.	126.	127.	156.
365.	451.	067.	1164.	1622.	1637.	1537	1370.	1013	865.	788.	710.	•	521.	464.	113.	307	297.	266.	237.	211.	189	159.	150	144.	136.	134.	132.	130.	.129.	120.	124.	120.	110.	106	103.	66	96	97.	96.	96.	954.	. 6	95.	95.	95.	95
11.92	12.00	12.17	12.25	12.42	12.50	12.50	19.71	12.63	12.92	13.00	13.00	13.17	13,13	13.42	13.50	13.28	13.75	13.63	13.92	14.00	19.00	14.25	14.33	14.42	14.50	14.67	14.75	14.92	15.00	12.00	15.25	15.33	15.50	15.58	15.67	15.83	15.92	16.00	16.17	16.25	16.23	76.41	16.50	16.67	16.75	
143											1																														1					i
11.55	12.09	12.10	12.15	12.25	12.30	12-35	12.4	12.50	12.55	13.00	13.05	OT . F.	13.20	13.25	13.30		13.49	13,50	13.55	14.0		14.19	15.20	14.25	14.30	14.40	14.45	14.55	15.00	12.02	15.15	15.20	15,30	15.35	15.40	15.50	15.55	91	16.10	16.15	16.29	10.67	16.35	16.40	16.45	16.50
		1.01	70.7	10.1	1.01	וֹפֿין			1.01	10.1	10-1	10.1		1.01	10.7	1001		1.01	10-1	10.1	10.1		10-1	10-1		1.01	10.1	10-1	10*1	10-1	101	1001	10-1	10-1			10.1		10.1	10.1	10-1			1.01	10.1	10.1

-

Ø PLATE D-32


<u> </u>	 	•	, - -	•	-	<u>•</u>		•	_	_	· 		•	: -	•	•		1	Ţ.	•	•	^	u	•	-	• • • •	'''	•	,	A 	•	- 	•	•	<u> </u>	
7	1		:		!						-				:		-		1							!				; ;		!			1	
			:								į		,		1				:				1		1				:	1		!		!		
	! !		:										İ		-				1										! !					!	:	
							-																													
603.6	103.6	303.6	103.6	303.6	303.5	303.5	10212	303.5	303.5	303.5	303.5	103.4	103.4	103.4																					!	
																																			1	
226.	226	225	224	224	223	223	222	222	222	221	221	221	220	220			276.87	178.	2.0	189	234								-			1			!	
103.	.00	98.	95.		76	9	976		65.	: :	93.	92.	900	79.			NO I											-				1				
									-							1	S S		2007	189.	234.														:	
###	;	; ;		::	:	;		\$	\$;;	3	;;	\$;					1		- [-			:	
22.25	20	8 °	12.	60	00	8	35		55	2 4	79	£.5	35	8			ZY-HOUR		7	71.5	234					}									:	
26.7	i		1		ł		i		1		- 1					9	-HOUR		98-1	2.00	163.	•												!		
													İ		RS	. '	9			*																
22.20	22.30	22.39	22.45	22.50	23.00	23.03	72.14	23.20	23.22	23.35	23.40	23.45	23,55	9	90 HOUR		PEAK	33.		• .															:	
5.5	9:	5	10.	70.	ē	0.	100		100		1.0	5.5	0	1.02	£ 13.		79.	SE	ES	.												-		1		
															AT TIME			CAS	3	Š	HOUS C															
															125.						1													1	;	
			!												15											1			1 1			!				
			:				1				1				UTFLOX														i i			-		!	1	
							1								PEAK OUTFLOW								:						:							
			1		-		i									 -							-			 	 1		<u> </u>	اٰا	PL	A	TE	D		3

٠, (\approx		'	<u>. </u>	<u> </u>		· 			-	<u>.</u>	7	<u> </u>		? *	 ,			-	7, 7	2.70		27,	iΖ	4		.	<u></u>		-
>		! !							1	-													į							
	•	1	•	• •	• •		1	• •	•	•	: '		• • •	• •	•		• •	1	• •	•	•	•	•	•		• •		•	•	•
					1															-										
	.0	, · ·]		••			••						• •			•		• •	1	•			•		••				•
	6					:																								
				•									╡.						• •		•		• •			٠.				
	1000																						ļ							
	9	• •		•			٠ ا	• •		.	:								٠.		•		• •				•		•	
	1600.																											:		
	1400.	 ••	1.	• •	• •	•	• -	• •	-	•			•	• •	•			-	• •	-	•		•		. •			٠.		•
	=									1																				
	200.	•	•	•	• •		•	• •	•	•		•	•	• •	•		• •		• •		•	•	• •	• •	•	• •		•	•	•
200	/EO FL						1		-	•	:																			
STAT10N000002	1000.	• •	•	•	••	•	•	٠ •	1	•		• •	•	• •	•		• •		• •	•	•		• •	• •	•	• •	•	:	4 •	•
STATI	ANO					•			-													9								
	INFLOALIS, GUTFLOAIGS AND GRSERVED FLOATS]		•	•		••]					• '					••	1	•				1	• •	*		•	•
	3					•								•					٠.								9	:		
	909 600																													
	INFL.			•			٠ إ	• •		.		∤	┥.	•				.			•		•							
	2					****																								
	200.		┥.	•				• •		•			1.	•				. }	• •		•	7	• •	• •		٠.			-	•
	Ā					****														1							1			
	6		15-	32	==		121	32	92:		201:- 211	241	251	271	201	31				7.			125	461	196				1	
• 0 VF •	1	202	22	35	9;	ង្គន	35	25	225	1	3 4 5	2.5	30	50	125	2 2	2.40	2.2	3.83	8:3	3.15	25.5	35	3.4		28	8:	5	32	2

. • • • • •••••••••••• • • • • • • -. • • • • • • • • • • • • . . • • . \$ 5.00 601 \$ 5.00

ſ ٠.; 9.551190 1 10.001200.1... 10.001202 1 10.20120 1 10.20120 1 10.30120 1 10.30120 1 10.30120 1 10.50130 1 11.00130 1 11.00130 1 11.00130 1 11.20130 0 11.30130 0 PLATE D-36

2 | 15.05181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 15.20181 | 1 0 | 10.20181 | 1 0 | 10.20181 | 1 0 | 10.20181 | 1 0 | 10.20181 | 1 0 | 10.20181 | 1 0 | 10.20181 | 1 0 | 10.20181 | 1 0 | 10.20181 | 1 0 | 1 0.20181 | 1 0 | 1 0.20181 | 1 0 | 1 0.20181 | 1 0 | 1 0.20181 | 1 0 | 1 0.20181 | 1 0 | 1 0.20181 | 1 0 | 1 0.20181 | 1 0 | 1 0.20181 | 1 0 | 1 0.20181 | 1 PLATE D-37 "



	•	RUMSE SUMMARY, AVERAGE FLOW IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)	IVERAGE FLO AREA IN	M IN CUBIC	FEET PER	SECOND (CU	BIC METERS	PER SECOND)	>	<u>'</u> ~
EURING TO GOODO (23.16) 1.24 1.24 1.24 1.24 1.24 1.24 1.24 1.24	e i	HYDROGRAPH AT	100000	PEAK 1637.	6-HOUR 363.	24-HOUR	72-HOUR 111.	AREA		((
		AQUTED 10	000000	825. 23.361(1	- 1	95.	3.261 3.261		• •
										•
	•									<u> </u>
	•								The label of the control of the cont	
		,								*
						,				<i>•</i>
	i i i									•
										,
										,
										,
	I i i									
										<i>(</i> *)
	0									
	PL				}					1111
	ATE									, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
										*

) 13.00 DURATION OVER TOP HOURS 4.83 SUMMARY OF DAM SAFETY ANALYSIS SPILLWAY CREST 802.20 MAXIMUM DUTFLOW CFS 825. INITIAL YALUE 802.20 188. 0. HAXIMUM DEPTH OVER DAM .93 ELEVATION STORAGE DUTELON RESERVOIR W.S.ELEV 805.53 RAILG PNF 0.00 PLAN 1 PLATE 0-40'